

# MOODY FIRE UPDATE

---

## Feb. 10, 2023 Report

by aldeptenvironmentalmanagement | Feb 10, 2023 | ADEM | 0 comments

### Site condition:

- Smoke can be observed where work is being conducted and a few areas on section B
- Odor can be detected on site
- Surface conditions are damp throughout the site

### Activity:

- Section B is the focus of work, with grading of this section using available materials that are on site

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

# MOODY FIRE UPDATE

