

MOODY FIRE UPDATE

Feb. 11, 2023 Report

by aldeptenvironmentalmanagement | Feb 13, 2023 | ADEM | 0 comments



Site Conditions:

- Wet in most areas of the site as it is raining
- Smoke is visible where work is being conducted on the northwest end of Section B and small, visible spots of smoke along the northwest side of Section A

Activities:

- Work continues to grade the slope around the north and west edges of Section B

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

