

MOODY FIRE UPDATE

Feb. 1, 2023 Report

by aldeptenvironmentalmanagement | Feb 1, 2023 | ADEM | 0 comments



Site Conditions:

- Site is muddy due to ongoing rain
- Smoke is less visible than yesterday

Activities:

- 40 loads of material from the borrow pit have been moved to the site.
- Grading on the southwest slope and more work on the northeast area of the site is continuing today.
- More regulated solid waste was observed in the staging area.

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

