

MOODY FIRE UPDATE

Feb. 12, 2023 Report

by aldeptenvironmentalmanagement | Feb 13, 2023 | ADEM | 0 comments



Site Conditions:

- No smoke observed in Section A and smoke is visible where work is being conducted on the northwest end of Section B
- Hint of odor at the site

Activities:

- Work is being done on the northern and northwestern slopes of Section B, including grading work
- New air monitoring equipment station is being created at the request of local residents

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

