

MOODY FIRE UPDATE

Feb. 13, 2023 Report

by aldeptenvironmentalmanagement | Feb 13, 2023 | ADEM | 0 comments



Site Conditions:

- Less smoke was visible where work is being conducted on the northwest end of section B, and little to no smoke along the northwest side of section A
- Odor can be detected throughout the site, and more noticeable close to where work is being done
- Wet in most areas, with noticeable areas drying out from the weekend rainfall

Activities:

- Similarly to the previous day, the contractors are working on the northern area, Section B, mostly grading the slope around the north and west edges of that area
- Machine maintenance being conducted at the borrow pit

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

