

# MOODY FIRE UPDATE

---

## Feb. 14, 2023 Report

by aldeptenvironmentalmanagement | Feb 14, 2023 | ADEM | 0 comments



### Site Conditions:

- Site is muddy with little smoke observed in the southern section but more in the northern section, where a majority of work is taking place

### Activities:

- Grading and dirt work is taking place today
- Rip rap is being installed for erosion and sedimentation control
- Wattles are being installed along the southern/southwestern slope of the site

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

## MOODY FIRE UPDATE

