

MOODY FIRE UPDATE

Feb. 19, 2023 Report

by aldeptenvironmentalmanagement | Feb 21, 2023 | ADEM | 0 comments



Site Conditions:

- Very little smoke can be observed on the north end where work is being conducted

Activities:

- Crews are applying riprap to the northeast portion of the site
- Work is being done to slope the north and northwest portion of the site
- Tree debris is being moved

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

