

MOODY FIRE UPDATE

Feb. 23, 2023 Report

by aldeptenvironmentalmanagement | Feb 23, 2023 | ADEM | 0 comments



Site Conditions:

- Smoke can be observed in a few areas along the northern slope of Section A but not in other areas

Activities:

- Additional material will be placed in Section A that is smoldering
- Stone will continue to be placed through the site as a means of erosion control, mainly along Section A today

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

