

# MOODY FIRE UPDATE

---

## Feb. 24, 2023 Report

by aldeptenvironmentalmanagement | Feb 24, 2023 | ADEM | 0 comments



### Site Conditions:

- Surface conditions are damp with no standing water
- Smoke barely visible in northwest sections and in localized areas
- Odor discernible only on-site

### Activities:

- Additional cover being applied to localized areas of smoke
- Continuing with road building into north areas of the site to accommodate haul trucks
- Road repaid continuing on Annie Lee Road
- BMP (fencing, waddles, check dams, etc.) are in place and maintained at the borrow pit and the site

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

## MOODY FIRE UPDATE

