

MOODY FIRE UPDATE

Feb. 25, 2023 Report

by aldeptenvironmentalmanagement | Feb 27, 2023 | ADEM | 0 comments



Site Conditions:

- Smoke can be observed in a few areas on the western side of Section B
- Odor can be detected throughout the site
- Surface conditions are very damp due to rain

Activities:

- Grading work continues on the western areas of Section A and B, and the northern area of Section B
- 93 loads of off-site borrow materials were delivered
- 220 loads of on-site borrow materials have been used thus far
- Road to the northern part of Section B is being constructed

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

