

MOODY FIRE UPDATE

Feb. 27, 2023 Report

by aldeptenvironmentalmanagement | Feb 27, 2023 | ADEM | 0 comments



Site Conditions:

- No smoke is observable
- Odor still slightly noticeable
- Erosion controls appear to be effective with minimal erosion observed

Activities:

- Grading and filling operations on the western and northern portions of the site are currently underway
- Weather permitting, approximately 150 loads of fill dirt will be brought to the site today
- Stone continues to be placed around the site to reduce runoff and erosion

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

