

# MOODY FIRE UPDATE

---

## Feb. 3, 2023 Report

by aldeptenvironmentalmanagement | Feb 3, 2023 | ADEM | 0 comments



### Site Conditions:

- Consistent smoke is emanating from the north portion of the site.

### Activities:

- Grading and filling operations have been performed at the north and northwest portions of the site.
- Site is being prepared to receive approximately 150 loads of dirt from the borrow pit tomorrow.
- Air monitors will be checked today and recalibrated, if needed.

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

## MOODY FIRE UPDATE

