

MOODY FIRE UPDATE

Feb. 7, 2023 Report

by aldeptenvironmentalmanagement | Feb 7, 2023 | ADEM | 0 comments



Site conditions:

- Smoke was observed at the site but it is significantly less than in previous days

Activities:

- Grading and other dirt work is continuing
- Rip rap and other stones have been brought in for erosion control, primarily on the western slope
- Approximately 158 truck loads of material from the borrow pit are planned to be brought to the site today

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

