

MOODY FIRE UPDATE

Feb. 9, 2023 Report

by aldeptenvironmentalmanagement | Feb 9, 2023 | ADEM | 0 comments

Site Conditions:

- Smoke is visible in the northwest and north sections
- Areas with smoke are not overwhelming and remain traversable on foot with one exception in the northwest portion
- Light odor is present at the site and up to 0.1 mile outside the site perimeter

Activities:

- Grading, blading and cover operations continue on the northwest and north portions of the site
- 133 loads of material from the borrow site were delivered yesterday
- Maintenance and cleaning is being performed on the machinery at the borrow pit

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

