

# MOODY FIRE UPDATE

---

Jan. 31, 2023

by aldeptenvironmentalmanagement | Jan 31, 2023 | ADEM



Contractors are continuing to grade the southwest slope of the site, and grading is occurring on the northeast slope.

- Regulated solid waste, which consists mostly of dimensional lumber, is being removed and staged in a separate area. Scrap tires are also being removed and staged in a separate area.
- Approximately 100 loads of soil per day are being retrieved from the borrow pit.

Borrow Pit:

- Silt fencing and an exit pad were installed at the entrance/exit of the pit to minimize sedimentation and tracking offsite.



The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

# MOODY FIRE UPDATE

