

# MOODY FIRE UPDATE

---

## March 13, 2023 Report

by aldeptenvironmentalmanagement | Mar 13, 2023 | ADEM | 0 comments



### Site Conditions:

- Site is wet with mud in various locations
- Smoke has not been observed
- Odor is present

### Activities:

- EPA continues to monitor progress being made at the site
- The contractor is hauling loads of soil materials staged within the site to grade areas being prepared for seeding and hay mat application
- No loads of fill materials will be hauled from the borrow pit today, and none are expected in the coming days

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

## MOODY FIRE UPDATE

