

March 16, 2023 Report

by aldeptenvironmentalmanagement | Mar 16, 2023 | ADEM | 0 comments



Site Conditions:

- No smoke detected on site
- Odor detected throughout the site

Activities:

- Material is being moved from the northern area, Section B, to the middle of the site
- The majority of the southern section, Section A, has been covered with hay and grass seed, and grass is starting to sprout in a few areas
- Work being performed today and for the next several days will include grading and preparing the rest of the site to be covered with hay and grass seed
- EPA personnel are collecting air samples for testing at 10 points near the site

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

