

MOODY FIRE UPDATE

March 21, 2023 Report

by aldeptenvironmentalmanagement | Mar 22, 2023 | ADEM | 0 comments



Site Conditions:

- Smoke was observed on the southern section, and odor was prevalent throughout the site
- Grass is growing throughout the southern section

Activities:

- Grading and compacting continued on the northern section, and some hay mats had been installed
- The northern section is expected to be seeded in the next couple days

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

