

MOODY FIRE UPDATE

March 23, 2023 Report

by aldeptenvironmentalmanagement | Mar 23, 2023 | ADEM | 0 comments



Site Conditions:

- Odor is only present at the entrance and southern portions of the site
- Most of the site is now covered with hay and has been seeded

Activities:

- Workers will continue to lay hay and seed the northwestern slope
- Tree service crew plans to be on site Monday to remove approximately 40 trees around the site
- No work is planned for weekend

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

