

MOODY FIRE UPDATE

March 28, 2023 Report

by adem | Mar 29, 2023 | ADEM | 0 comments



Site Conditions:

- Odor detected at the top of the hill in the southern section

Activities:

- Workers placed dirt and clay on areas in the southern section to fill cracks and address odor
- Seed and straw placed on the northwestern slopes
- Tree service removed trees
- Grass growth was monitored

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

