

MOODY FIRE UPDATE

March 29, 2023 Report

by adem | Mar 29, 2023 | ADEM | 0 comments



Site Conditions:

- Site dry, with some mud and water in drainage areas.

Activities:

- More trees removed
- Water applied to cracks in the southern section where clay was added the previous day
- Seed and straw placed in additional areas

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

