

MOODY FIRE UPDATE

March 7, 2023 Report

by aldeptenvironmentalmanagement | Mar 8, 2023 | ADEM | 0 comments



Site Conditions:

- Site was mostly dry with occasional muddy spots.
- Faint smoke was observed at the top of the southern hill.
- Odor was faint, but noticeable throughout the site.

Activities:

- Crews continued to move material from the borrow pit to the site.
- Compacting and grading performed.
- Straw mats installed throughout the southern section of the site to prevent the slopes from eroding.
- Crews excavated area of faint smoke on southern hill and doused with water to extinguish it.

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

