

MOODY FIRE UPDATE

March 8, 2023 Report

by aldeptenvironmentalmanagement | Mar 8, 2023 | ADEM | 0 comments



Site Conditions:

- No smoke observed on the site
- Odor can be detected at the top of the hill on the southern section of the site

Activities:

- Excavated area at the top of the hill on the southern section has been backfilled
- Grading and BMP installation and maintenance taking place, with fill material being brought in from the borrow pit
- 104 truckloads of material were brought in yesterday from the borrow pit, with about the same amount expected today

The Alabama Department of Environmental Management (ADEM) has created Moody Fire Update to inform the public of ongoing efforts to extinguish the fire at the Environmental Landfill LLC vegetative waste disposal site near Moody.

MOODY FIRE UPDATE

